(E) PLOT SCALE: 1=4 | DWG. SCALE: 4 | Axxxxx







NOTE:
THE SOURCE MOUNTS TRIS FASTENERS TO THE TOP OF THE SOURCE BRACKET. SEE THE SOURCE PROPERTIES PDF (LATEST) FOR THE PARTS LIST INCLUDED WITH THE SOURCE.

| | | | |
|---|---|---|---|
| 8 | PURCHASE | 1/4" SPRING WASHER | SEE SOURCE 12 |
| 7 | STANDARD | 1/4-20 X 1-1/4 LG. SOCKHEAD SCREW | 304L 12 |
| 6 | STANDARD | 1/4-20 X 1/2 LG. SOC HD. CAP SCREW | 304L 12 |
| 5 | PURCHASE | 1/4 DIA X 1/2 SHORT CYLINDRICAL DOWEL | SEE SOURCE 2 |
| 4 | PURCHASE | SRM | SEE SOURCE 1 |
| 3 | 30700-30000 | SRM-MOUNT SPACER | 1 |
| 2 | 30700-30000 | SRM PLATE | 1 |
| 1 | 30700-30000 | SUPPORT BRACKET | 1 |

ITEM QTY PART NUMBER DESCRIPTION

ARGONNE NATIONAL LABORATORY

A07644

DRAWN BY: [illegible] 10/31/07
CHECKED BY: [illegible]
APPROVED BY: [illegible]
APPROVED BY: [illegible]
APPROVED BY: [illegible]

ADVANCED PHOTON SOURCE
SOURCE
SUPPORT BRACKET
ASSEMBLY
JAW & SOURCE SUPPORT BRACKET ASSEMBLY

SEE PARTS LIST

30700-30000-00