

PSS Gen-1 Upgrade Task Assignments
 For
 APS Project Review 2007
 (7-18-06)

Task	Comments	Task Leader	Team Members	Rank
PLC H/W Platform Upgrade – (Items 9,19)	Hardware components in Chain B ladder logic and PLC obsolescence	Servino	Belcher, McNamara, Budz	1
PSS Chain B software upgrades – (Items 9,13,14)	Software components in Chain B change to ladder & G3 features	Servino	Fagan, Hogrefe , Nguyen	1
PSS Chain A software upgrades – (Items 13,14)	Software components in Chain A change to G3 features	Servino	Fagan, Forrestal, Boron	1
PSS Testing Upgrades – (Item 12)	Safety aspects of testing (H/W & S/W)	Hawkins	Fagan, Forrestal,	1
PSS Testability Upgrades – (Item 13)	Provide non-intrusive testing features.	Belcher	Fagan, McNamara, Budz	1
PSS software architecture Upgrade – (Item 14)	Develop consistent coding style guide	Servino	Nguyen, Boron, Forrestal, Fagan	1
PSS Shutter Interface Upgrades – (Item 21)	Implement the new FE and BL shutter interfaces	Belcher	Budz, Friedman, Forrestal	1
PSS DIW Interface Upgrade – (23)	Implement the new DIW interface	Belcher	Budz, Friedman	1